

Fluorescent Lighting

- Developed around turn of century
- Commercially available in 1938 by GE
- Presented at 1939 Worlds Fair
- Made efficient lighting possible during WWII in factories and warehouses

Copyright SYTEK Consultants

1

Fluorescence is the conversion of one frequency of electromagnetic radiation to another frequency by a material

Copyright SYTEK Consultants

2

Fluorescent Lighting

- Operates by maintaining a low pressure mercury arc in a linear glass tube
- Mercury arc produces UV radiation
- UV strikes phosphor on inside of lamp
- Phosphor converts UV to visible light
- Most of input power creates light, not heat

Copyright SYTEK Consultants

3

Fluorescent Lamps

- Lamps are a linear soft light source
- Last between 10,000 to 25,000 hours
- Run cool (about 150°F at their ends)
- Very efficient source of light
 - About 5 times more light per watt than Incandescent Systems

Copyright SYTEK Consultants

4

Fluorescent Lighting Drawbacks

- Lamps require additional equipment
 - Ballast
 - Starter
 - More wire
- Lamps contain Mercury
- Cost more to install

Copyright SYTEK Consultants

5

Why do fluorescent lamps need a ballast?

- Lamps require more than 120 Volts to start.
- Once started, lamps want to draw all the available current.
- Once started, lamps will immediately burn out without ballast
- Lamps have negative resistance behavior

Copyright SYTEK Consultants

6

Incandescent v. Fluorescent

- Incandescent filament resistance goes up when it is heated, thus limiting the current flowing through the lamp.
- In fluorescent lamps, the “resistance” of the mercury arc declines as more current flows through it.

Copyright SYTEK Consultants

7


Purpose of a Ballast

- The ballast has several purposes:
 - Transform the input voltage to high enough level to strike the arc in the tube
 - Limit the current flowing through the tube (typically between 0.2 to 0.8 Amps)

Copyright SYTEK Consultants


8

Lamp Construction



Copyright SYTEK Consultants


9



Copyright SYTEK Consultants

10


Lamp Operation



Copyright SYTEK Consultants

11

Lamp Operation



Phosphor Coated Glass

Clear Glass

Copyright SYTEK Consultants

12

Lamp Starting



Basic Fixture Types

- Recessed "T bar" troffers
 - Most of fixture above ceiling
- "C" channel strips
 - Typically suspended or surface mounted
- Low Profile Wrap Arouds
 - Surface mounted
 - Has lens "wrapped" around fixture

Copyright SYTEK Consultants

14

Typical Troffer



Copyright SYTEK Consultants

15

Interior of Troffer



Copyright SYTEK Consultants

16

Interior of Troffer



Copyright SYTEK Consultants

17

Top Surface of Troffer



Copyright SYTEK Consultants

18

“C” Strip Fixture



Copyright SYTEK Consultants

19


Interior of “C” Strip Fixture



Copyright SYTEK Consultants


20

Low Profile Wrap Around



Copyright SYTEK

Interior of Low Profile Wrap Around Fixture



Copyright SYTEK Consultants

22

Fluorescent System Types

- Basically three common types of systems
 - Pre-Heat
 - Rapid Start
 - Instant Start
- Can be identified by wiring system

Copyright SYTEK Consultants

23

Various Fluorescent Ballasts




Copyright SYTEK Consultants

24

Pre-Heat System

- Mostly used today in desk lamps
- Original system
- Often used starter or push and hold button



Copyright SYTEK Consultants

25

Starter




Copyright SYTEK Consultants

26

Rapid Start System

- Lamps come on quickly, but with visible delay
- Ends of lamps heated inside
- Long lamp life



Copyright SYTEK Consultants

27

Rapid Start Lamp Ends




Copyright SYTEK Consultants

28

Instant Start System

- Lamps come on instantly
- Use high voltage to blast arc down tube
- Short lamp life
- Lower cost to buy and install



Copyright SYTEK Consultants

29

Instant Start Lamp End



Copyright SYTEK Consultants

30

Lamps Sizes

- T-12
 - 4, 6 & 8 foot
 - Still very common
- T-8
 - Used mostly with lower current electronic ballasts
 - Physically interchangeable with T-12 lamps
 - Not electrically interchangeable with T-12 lamps
- T-5
 - For electronic ballasts only
 - Very efficient

Copyright SYTEK Consultants

31



Copyright SYTEK Consultants

32

Purpose of a Ballast

- The ballast has several purposes:
 - Transform the input voltage to high enough level to strike the arc in the tube
 - Limit the current flowing through the tube (typically between 0.2 to 0.8 Amps)

Copyright SYTEK Consultants

33

Types of Ballasts

Magnetic
Ballasts

Electronic
Ballasts

Copyright SYTEK Consultants

34

Magnetic Ballasts


- Original type developed
- Proven technology
- Operate lamps at 60 cycles per second
- Lower efficiency light source
- Fewer parts, high reliability
- Lower cost

Copyright SYTEK Consultants

35

Magnetic Ballast Operation


MAGNETIC BALLAST BLOCK DIAGRAM



Copyright SYTEK Consultants

36

Magnetic Ballast Interior



Copyright SYTEK Consultants

37

Electronic Ballasts


- Very high operating efficiency
- Operate lamps at high frequency
 - (20 to 40 thousand cycles per second)
- Large number of components inside
- Expensive compared to magnetic ballasts
- Becoming more popular
- Required to meet most energy codes

Copyright SYTEK Consultants

38

Electronic Ballast Operation


BLOCK DIAGRAM OF ELECTRONIC BALLAST OPERATION



Copyright SYTEK Consultants

39


Electronic Ballast Interior



Copyright SYTEK Consultants

40

Electronic and Magnetic Ballasts



Copyright SYTEK Consultants

41

Potting Compound

- Softens around 250 to 270 F
- "Liquid" at about 360 to 380 F
- Inserted into ballast at about 380 to 400 F
- Flash point > 500 F
- Auto-ignition temperature > 800 F

Copyright SYTEK Consultants

42

Fluorescent Fixtures as Fire Causes

- Fires caused by wiring in fixture
- Fires caused by failures at the lamp holders
- Fires caused by the ballast

Copyright SYTEK Consultants


43

Fluorescent Fixture Fire Causes

- Pinched and arced wires
 - Rare
 - Often arcing is result of fire heat impingement
- Overheated /Arcing lamp holders
 - Usually contact with combustibles or
 - Close proximity of lens to lamp holder
- Arc penetrations through ballast case
 - May be through top, bottom or sides

© SYTEK Consultants

Typical Reflector




© SYTEK Consultants

Fires Caused by Wiring in Fixture


- Fairly rare. Most arcing in fixtures is caused by fire attacking the fixture.
- Arcing in fixture may penetrate fixture body.
- Arcing may ignite light fixture lens.
- Pinched wire may arc producing sparks.

Copyright SYTEK Consultants

46



Result of Wire Pinched Between
Reflector and Channel



© SYTEK Consultants

Fire Induced Arcing in Fixture

- Fixture is a heat absorbing “fin”.
- Think of the fixture as a piece of conduit.
- Should be considered during arc mapping.

Copyright SYTEK Consultants

48

Fire Damage to Fixture Wiring




Copyright SYTEK Consultants

49



Copyright SYTEK Consultants

50



Copyright SYTEK Consultants

51

Fires Caused By Lamp Holders

- Typically result of poor connection to lamps
- Improper seating of the lamps
- Improper spacing of lamp holders
- Improper installation of lamp holders
- More common with higher current lamps
- Generally only occurs with Instant Start circuits
- Ballast is designed to maintain an arc and it will!

Copyright SYTEK Consultants

52

Fires Caused by Lamp Holders

- Lamp holders are made of some what retardant materials.
- Lamp holders may be made of thermoset or thermoplastic materials.
- Arcing may ignite dust or lint.
- Typically involves fixtures with lenses or combustibles in close proximity to lamp holders.
- Typically not associated with troffers.

Copyright SYTEK Consultants


53




Copyright SYTEK Consultants

54

Proper Insertion




Proper Insertion



Copyright SYTEK Consultants

55


Proper Insertion



Copyright SYTEK Consultants

56

Incorrect Insertion



Copyright SYTEK Consultants

57



Photo Courtesy of ATF National Laboratories Fire Research Laboratory




Photo Courtesy of ATF National Laboratories Fire Research Laboratory




Photo Courtesy of ATF National Laboratories Fire Research Laboratory

Warning Sticker



Copyright SYTEK Consultants

61

Locking Lamp Holders



Copyright SYTEK Consultants

62


Bi Pin Lamp Holder Overheating



Copyright SYTEK Consultants

63

Bi Pin Lamp Holder Overheating



Copyright SYTEK Consultants

64

Bi Pin Lamp Holder Overheating



Copyright SYTEK Consultants


65

Damage to Lamp



Copyright SYTEK Consultants

66



Copyright SYTEK Consultants

67




Copyright SYTEK Consultants

68




Copyright SYTEK Consultants

69




Copyright SYTEK Consultants

70




Copyright SYTEK Consultants

71



Copyright SYTEK Consultants

72





Copyright SYTEK Consultants

73




Copyright SYTEK Consultants

74




Copyright SYTEK Consultants

76



Copyright SYTEK Consultants

77



Copyright SYTEK Consultants

Some Ballast Fire Producing Failures

- Ballast Overheating
- Upward arcing events
- Downward arcing events
- Arcing through the side of the fixture

Copyright SYTEK Consultants

79


Causes of Ballast Overheating

- Shorting of coil windings in the transformer
- Failure of power capacitor
- End of life of instant start lamps
- Internal arcing
- Improper voltage or lamps

Copyright SYTEK Consultants

80


Overheated Coil in Ballast



Copyright SYTEK Consultants

81


Overheated Coil in Ballast



Copyright SYTEK Consultants

82

Coil Failure In Ballast



Copyright SYTEK Consultants

83

Coil Failure In Ballast



Copyright SYTEK Consultants

84

Coil Failure In Ballast



Copyright SYTEK Consultants

85

Coil Failure In Ballast



Copyright SYTEK Consultants

86

Arc Penetrations Through Ballast Case

- Probably leading cause of *magnetic* ballast fires
- Can occur in thermally protected ballasts
- Can burn hole through fixture
- Can ignite materials above fixture such as:
 - Wood
 - Plywood
 - Combustible ceiling tiles

Copyright SYTEK Consultants

87

Arc Penetrations Through Ballast Case

- Can occur through side of ballast case
- Can exit top or side of fixture and ignite:
 - Lens
 - Combustibles below
 - Lint or dust
 - Light weight materials

Copyright SYTEK Consultants

88






Copyright SYTEK Consultants

89



Copyright SYTEK Consultants


90





Copyright SYTEK Consultants

97



Copyright SYTEK Consultants

98



Copyright SYTEK Consultants

99

Multiple Arc Penetrations



Copyright SYTEK Consultants

100



Copyright SYTEK Consultants

101

Ballast Protection

- Between 1940's and early 1960's, most ballasts in heavy metal fixtures mounted away from combustibles.
- Around 1960, most manufacturers began to develop protection systems.
- First NEC code requirements in mid- 1960's

Copyright SYTEK Consultants

102

Ballast Protection History

- Originally fuses for each ballast recommended
- Single shot thermal protectors (~260°F to 270°F) came next
- Self-resetting thermal protectors (~ 230°F) became common method of protection
- Internal capacitor protectors developed

Copyright SYTEK Consultants

103

Thermal Protection History

- By 1961, most manufacturers had single shot thermally protected ballasts available
- In 1962, GSA required thermal protection in ballasts for government buildings
- In 1965, NEC required new fixtures to “incorporate ballast protection”
- The 1965 NEC requirement was postponed to 1967

Copyright SYTEK Consultants

104

Thermal Protection History

- UL asked for NEC requirement to be moved back until 1968 - 1969
- UL begins “Class P” listing of thermally protected ballasts
- UL listing criteria favors self resetting thermal protectors in magnetic ballasts

Copyright SYTEK Consultants

105

Thermal Protection History


- 1981 NEC states:
 - “Where fluorescent fixtures are installed indoors, the ballasts shall have thermal protection within the ballast. Replacements for these ballasts shall also be integrally protected”
- From 1968 to 1984, Non-thermally protected ballasts could be replaced with non-thermally protected units.
- 1984 NEC required all replacement ballasts to be thermally protected.

Copyright SYTEK Consultants

106

Fire History

Fluorescent Ballast Fires




Source: IAEE News 1978-1983

Copyright SYTEK Consultants

107


Typical Thermal Protectors



Copyright SYTEK Consultants


108

Self Re-setting Thermal Protectors



Copyright SYTEK Consultants

109




Copyright SYTEK Consultants

110




Copyright SYTEK Consultants

111



Copyright SYTEK Consultants

112



Copyright SYTEK Consultants

113

Resetting Thermal Protectors

- Most set at 221°F to 239°F
- May not reset until cooled below 185°F
- Must be able to operate 10,000 times under load
- Most are able to operate about 14,000 to 16,000 times before failure
- Typical cycle is once every 30 to 45 minutes

Copyright SYTEK Consultants

114

How Are Ballasts Evaluated After A Fire?

- Post fire examination of ballasts is destructive in nature.
- Experts should perform the examination.
- Examination should be in laboratory setting.
- X-Rays are preferred before disassembly.
- Fairly well established protocols exist.

Copyright SYTEK Consultants

115


How Are Ballasts Evaluated After A Fire?

- Potting Compound Condition
 - Low heat - shiny black, soft
 - Can be re-melted
 - Medium heat - hard, tough dull black
 - Barely re-meltable
 - More Heat - hard, brittle, porous gray/black
 - Bubble size depends upon rate of heating
 - More heat - White powder (remains of sand)
 - Final stage - glass like fusing of sand

Copyright SYTEK Consultants

116

Coil Failure In Ballast



Copyright SYTEK Consultants


117

Cross Section of Ballast With Internal Overheating Due to Coil Failure




Copyright SYTEK Consultants

118



Copyright SYTEK Consultants


119



Copyright SYTEK Consultants


120

Thermal Protector Testing




121

Thermal Protector Testing




122

Typical Fire Damaged Protector




Copyright SYTEK Consultants



Copyright SYTEK Consultants

124



Copyright SYTEK Consultants

125



Copyright SYTEK Consultants


126

Analysis of Electronic Ballasts

- Does not have the “fire endurance” of a magnetic ballast.
- Do not have the general overheating like magnetic ballasts.
- Overheating is a component phenomena.
- Look for localized damage to the circuit board.
- Look for arc penetrations of the case.
- Examine the fuse.


Copyright SYTEK Consultants

127




Copyright SYTEK Consultants

128




Copyright SYTEK Consultants

129



Copyright SYTEK Consultants

130



Copyright SYTEK Consultants

131




Copyright SYTEK Consultants

132





Copyright SYTEK Consultants

133




Copyright SYTEK Consultants

134




Copyright SYTEK Consultants

135




Copyright SYTEK Consultants

136



Copyright SYTEK Consultants

137




Copyright SYTEK Consultants

138



Copyright SYTEK Consultants

139



Copyright SYTEK Consultants

140


Protection of Electronic Ballasts

- Early electronic ballasts had resetting thermal protectors.
- Most electronic ballasts today use fuses instead of thermal protectors
- UL allows electronic ballasts to be listed as "Class P" with fuses

Copyright SYTEK Consultants


141

Typical Fuse




Copyright SYTEK Consultants

142




Copyright SYTEK Consultants

143



Copyright SYTEK Consultants

144



Fixture Paint Condition

- Fixture paint condition often misleading
- Must be used with caution
- NFPA 921 warns "Care should be exercised when evaluating heat damage patterns on painted steel surfaces"

Copyright SYTEK Consultants

146


Fixture Paint Condition

- Paints will
 - Discolor slightly by 400°F
 - Noticeably darken by 550°F
 - By 700°F will begin to lighten again
 - At 1000°F, paint will turn to chalky white powder

Thus, cooler locations may have darker color paint

Copyright SYTEK Consultants

147



Copyright SYTEK Consultants

148


Fire Heated Fixtures





Copyright SYTEK Consultants


151



Copyright SYTEK Consultants

152

Over-heated Ballast Pattern



Copyright SYTEK Consultants

153

How Are Fluorescent Fixture Fires Investigated?

- Find point of origin first!
- Determine origin both horizontally and vertically
 - Was fire started above or below ceiling?
 - Was fire caused by drop down from above?
- Determine first fuel ignited
 - Was it in contact with fixture?
 - Is it combustible? Readily ignitable?

Copyright SYTEK Consultants

154

How Are Fluorescent Fixture Fires Investigated

It is not practical nor proper investigative technique to try to disassemble every ballast in a building to look for a cause of a fire. Identify any possible sources of ignition at the point of origin including light fixtures.

Copyright SYTEK Consultants

155

What To Do

- Document how fixture was mounted
- Document how the fixture was supplied with power
- Collect fixture, channel cover, wiring and lamp holders
- Leave ballast attached to fixture if possible
- Minimize damage to fixture
- Collect ceiling materials
- Gather exemplar fixtures

Copyright SYTEK Consultants

156

What NOT To DO

- **Dispose of fixture and channel cover**
- **Open or disassemble ballast**
- **Lose fixture wiring and lamp holders**
- **Remove and open thermal protector**
- **Energize the ballast**

Copyright SYTEK Consultants

157

Common Myths

- The ballast that leaked the most potting compound caused the fire.
- The lightest ballast caused the fire.
- The ballast that rattles the most caused the fire.
- The fire burned inside the ballast can for an extended time.
- Ballasts can not cause fires.
- Arc penetrations mean the breaker was defective.

Copyright SYTEK Consultants

158

Some Truths

- Ballast do cause fires.
- Lamp holders do cause fires
- Ballasts can “blow up”
- Some ballasts do contain PCB’s in their capacitors.

Copyright SYTEK Consultants

159

Example of Fluorescent Fixture Fire

**Overheating and Arcing in Ballast
Causes Low Density Ceiling
Fiberboard Tiles to Ignite**

160

Low Density Ceiling Fire



Copyright SYTEK Consultants

161

Low Density Ceiling Fire




Area Above Suspect Ballast

Copyright SYTEK Consultants

162


Top of Fixture After Fire



Copyright SYTEK Consultants

163


Side of Ballast After Fire



Copyright SYTEK Consultants

164


Base of Ballast After Fire



Copyright SYTEK Consultants


165

Ballast Coils



Copyright SYTEK Consultants

166



Copyright SYTEK Consultants

167

**Example of Long Term
Overheating of Ceiling
Material**

168



Photo by David Smith

Copyright SYTEK Consultants

169



Photo by David Smith

Copyright SYTEK Consultants

170



Photo by David Smith

Copyright SYTEK Consultants


171



Photo by David Smith

Copyright SYTEK Consultants

172



Copyright SYTEK Consultants

173




Copyright SYTEK Consultants

174



Copyright SYTEK Consultants

175



Copyright SYTEK Consultants

176




Copyright SYTEK Consultants

177

Example of Arc Penetration Causing a Fire

178

Fixture Position



Copyright SYTEK Consultants

179

Top of Fixture




Copyright SYTEK Consultants

180

Top of Fixture




Top of Fixture



Copyright SYTEK Consultants

182

Ballast Interior



Copyright SYTEK Consultants

183

Ballast Interior



Copyright SYTEK Consultants

184


Ballast Interior



Ballast Interior




Thermal Protector



Copyright SYTEK Consultants


187

Thermal Protector



TP failed to open
at up to 155C


Thermal Protector



Copyright SYTEK Consultants

189

Thermal Protector



90

Thermal Protector



Copyright SYTEK Consultants

191